

# FIELD INSPECTION REPORT

Date of Inspection : 02/12/2020		District: Urapalganj.	
Division : Mathura.		Length (km): 7.06 km.	
Name of the Road: Mingani (power House NH-85) to Arna Bazar.			
Scheme/Programme:		MAINTENANCE	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U U	
b)	Condition of Surfacing	S/U U	
c)	Riding Quality	S/U S	
d)	Road Camber	S/U S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No YES	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No YES	
g)	Compaction of flank/slope & raincuts if any	Yes/No NO	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U S	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N-A	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N-A	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No YES	
4.	Compliance History		
a)	Status of ATR's & any others	Not any	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

NAME: AFTAB ALAM  
AE  
DESIGNATION:

R. Kumar  
2/12/2020  
JC  
(Signature)  
2/12/20  
AE