

# FIELD INSPECTION REPORT

Date of Inspection : 03/12-2020		District: Gopalganj
Division : Halkani		Length (km): 11.80 km
Name of the Road: Halkani Se Kharitja Path		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U-'S'
b)	Condition of Surfacing	S/U-'U'
c)	Riding Quality	S/U-'U'
d)	Road Camber	S/U-'S'
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No - NO Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No - N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No - NO
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U-'S'
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U-'S'
c)	Condition of railings/slab/approach for Bridges	S/SRI/U-'N/A'
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No - NO
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	U

(Signature)

NAME:

MANOJ KUMAR

DESIGNATION:

A.E. RWD Halkani