

FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020	District: Muzaffarpur
Division : RWD WEST	Length (km): 2.81 km
Name of the Road: Improvement of Harchand, Saiy to Balnua Chowk, W. B. Shariyals Salona Village	
Scheme/Programme:	MAINTENANCE
Package No.: RM/MU/MUZ/19/0021	Road Id No.: 3150720/012
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S S/U
b)	Condition of Surfacing	S S/U
c)	Riding Quality	S S/U
d)	Road Camber	S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	H/A Yes/No
f)	Contraction Joints provided or not (CC Pavement)	H/A Yes/No
g)	Compaction of flank/slope & raincuts if any	Compacted Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	H/A S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No ATR

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Kishor Kumar
DESIGNATION: Executive Engineer