

Latitude: 26.080154
 Longitude: 85.099017
 Elevation: 55.55m
 Accuracy: 5.0m
 Time: 03-12-2020 14:58

FIELD INSPECTION REPORT

Date of Inspection : 3-12-2020		District: TAVAR
Division : R.W.D. MVZ - West		Length (km): 3.41km
Name of the Road: - 10th Bg - Dimplekoppa		
Scheme/Programme: MAINTENANCE		
Package No.: MR/MD/MVZ/19/0816		
Status of the Project: Ongoing/Completed/Under Maintenance		Road Id No.: 357202125
Work is a case of: New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	= 5 =
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

3-12-20
 (Signature)

NAME: Satya Narayan Dasgupta
 DESIGNATION: J.E.