

FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020	District: MUZAPPARPUR
Division : RWD WEST	Length (km): 1.8 km
Name of the Road: Madhuban gram ke Path se Kameshwar Pandey k ghar note hue kalmaai ghut	
Scheme/Programme:	MAINTENANCE
Package No.: RM/MV/MUZ/19/0019	Road Id No.: 31507203013
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S ✓ S/U
b)	Condition of Surfacing	S ✓ S/U
c)	Riding Quality	S ✓ S/U
d)	Road Camber	S ✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A Yes/No
f)	Contraction Joints provided or not (CC Pavement)	N/A Yes/No
g)	Compaction of flank/slope & raincuts if any	Compacted ✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U ✓
c)	Condition of railings/slab/approach for Bridges	N/A S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No ATR

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

201
03/12/2020
(Signature)

NAME: Raman Krishan

DESIGNATION: A.E