FIELD INSPECTION REPORT

Date of Inspection: 3		District: PATHA
Division: DAHAPUR		Length (km): 2.00 lem
Name of the Road: H	H30 00 Maka	dew other to madhopur.
Scheme/Programme:	MAINTENANC	E
Package No.: mR-	N/19-20 Danapu	Road Id No.:
Status of the Project:		ted/Under Maintenance
Work is a case of:		y/Up gradation/ Maintenance
*15/1 x x x	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	

Sl. No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	s/sri/u
3.	Road Furniture	125 25 25 26 27
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
**** ********************************	Gompliance History	
a)	Status of ATR's & any others	<u> </u>

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	5

Work not started

Subsh elanar hys

NAME:

DESIGNATION:

(Signature)