

FIELD INSPECTION REPORT

Date of Inspection :	02-12-2020	District:	Vaishali
Division :	Maharashtra	Length (km):	2.0 K.M
Name of the Road:	Matihauli Jinar to Akshaywatdwar NH-103.		
Scheme/Programme:	MAINTENANCE		
Package No.:	N.A	Road Id No.:	31507708033
Status of the Project:	Ongoing/Completed/Under Maintenance ✓		
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	U ✓SAU
c)	Riding Quality	SAU ✓
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N.A Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	N.A Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	N.A ✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N.A S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N.A S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

(Signature)

NAME: SHRABAN KUMAR PRASAD

DESIGNATION: A.E.R.W.D.