

# FIELD INSPECTION REPORT

Date of Inspection : 02-12-2020	District: Vaishali.
Division : Mahanagar	Length (km): 6.10 K.M
Name of the Road: N.H-103 Uchailh to Mahanagar SH Main Chowk.	
Scheme/Programme:	MAINTENANCE
Package No.: N.A	Road Id No.: 31507709043
Status of the Project:	Ongoing/Completed/Under Maintenance ✓
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. N.A	Yes/No
f)	Contraction Joints provided or not (CC Pavement) N.A	Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting N.A	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts N.A	S/SRI/U
c)	Condition of railings/slab/approach for Bridges N.A	S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature)   
 Shailendra Kumar.   
 2/12/20

NAME: Shailendra Kumar.

DESIGNATION: J.E RWD, Bidupur.