## FIELD INSPECTION REPORT

Date of Inspection: 02-12-20 District: Vargeta  Division:  Name of the Road: 21123 - 11 - 1	3
Scheme/Programme: MAINTENANCE  Package No.:  Status of the Project: Ongoing/Completed/Under Maintenance  Work is a case of: New Connectivity/Up gradation/ Mainten  Sl. No.  Parameters to be checked  1. Pavement  a) Road Junction condition  b) Condition of Surfacing (Mode: 200 m Surface Dameses)	vance /
Scheme/Programme: MAINTENANCE  Package No.:  Status of the Project: Ongoing/Completed/Under Maintenance  Work is a case of: New Connectivity/Up gradation/ Mainten  Sl. No.  Parameters to be checked  1. Pavement  a) Road Junction condition  b) Condition of Surfacing (Mode: 200 m Surface Dameses)	nance /
Status of the Project: Ongoing/Completed/Under Maintenance Work is a case of: New Connectivity/Up gradation/ Mainten Sl. No. Parameters to be checked  1. Pavement  a) Road Junction condition  b) Condition of Surfacing (Mode: 200 m Surface Dameses)	nance /
Work is a case of:  New Connectivity/Up gradation/ Mainten  Sl. No.  Parameters to be checked  1. Pavement  a) Road Junction condition  b) Condition of Surfacing (Mode: 200 m Surface Dameses)	nance /
Sl. No.  Parameters to be checked  1. Pavement  a) Road Junction condition  b) Condition of Surfacing (Mode: 200 m Surface Dameses)	nance /
Sl. No.  Parameters to be checked  1. Pavement  a) Road Junction condition  b) Condition of Surfacing (Mode: 200 m Surface Dameses)	The second secon
a) Road Junction condition b) Condition of Surfacing (Mote: 200 m Surface Dameze S	The second that the second second
b) Condition of Surfacing (Mote: 200 m Surface Dameze f	the district water to the same
b) Condition of Surfacing (Mote: 200 m Surface Dameze f	971
Mote: 200 m Surface Dameze S	<i>⊸</i> 8/U
c) Riding Quality	som (food) S/U
	-8/U
d) Road Camber .	S/U
e) Whether free from defects such as visible cracks aggregates in case of CC Pavement.	s, exposed Yes/No
f) Contraction Joints provided or not (CC Pavement)	N/A Yes/No
g) Compaction of flank/slope & raincuts if any	well and the Yes/No
2. Cross Drainage	
a) Condition of head walls in Hume pipe culverts including it	ts painting S/SRI/U
b) Condition of Abutment & Wing walls, Slab in RCC culver	
c) Condition of railings/slab/approach for Bridges	
3. Road Furniture	S/SRI/U
a) Whether sign boards/informatory/cautionary Board/km stones/Pavement road markings are provided and maintain	& 200m Yes/No
4. Compliance History	San Rapinson - 1970 South Land Control of St.
a) Status of ATR's & any others	

Overall Rating

0.00	
Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: RINKI KUMAN

DESIGNATION:  $\mathcal{J} \cdot \mathcal{E}$