

FIELD INSPECTION REPORT

Date of Inspection : 02/11/20 District: Nalanda.
 Division : Rajgir Length (km): 1.000 Km.
 Name of the Road: Nalanda Nisapur road to Jagdishpur via Mahanayapustham
 Scheme/Programme: MAINTENANCE 3054 MR New Maintenance P 2018
 Package No.: RM/NA/RAJ/19/0004 Road Id No.: 10200701031.
 Status of the Project: Ongoing Completed Under Maintenance ongoing.
 Work is a case of: New Connectivity/Up gradation/ Maintenance Maintenance.

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign board, Informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

✓ 'S'

Salvost Kumar.

(Signature) 21/11/20

NAME: