

# FIELD INSPECTION REPORT

|                                                                 |                       |
|-----------------------------------------------------------------|-----------------------|
| Date of Inspection: 3.12.20                                     | District: G.14.2000/1 |
| Division: G.14.2000/1                                           | Length (km): 2.57 km  |
| Name of the Road: M/R of G.14.2000/1                            | to B.14.2000/1        |
| Scheme/Programme: MAINTENANCE                                   |                       |
| Package No.:                                                    | Road Id No.:          |
| Status of the Project: Ongoing/Completed/Under Maintenance ✓    |                       |
| Work is a case of: New Connectivity/Up gradation/ Maintenance ✓ |                       |

| Sl. No.   | Parameters to be checked                                                                                             | Remarks   |
|-----------|----------------------------------------------------------------------------------------------------------------------|-----------|
| <b>1.</b> | <b>Pavement</b>                                                                                                      |           |
| a)        | Road Junction condition                                                                                              | S/U       |
| b)        | Condition of Surfacing                                                                                               | S/U       |
| c)        | Riding Quality                                                                                                       | S/U       |
| d)        | Road Camber                                                                                                          | S/U       |
| e)        | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No ✓  |
| f)        | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No ✓  |
| g)        | Compaction of flank/slope & raincuts if any                                                                          | Yes/No ✓  |
| <b>2.</b> | <b>Cross Drainage</b>                                                                                                |           |
| a)        | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U ✓ |
| b)        | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U ✓ |
| c)        | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U ✓ |
| <b>3.</b> | <b>Road Furniture</b>                                                                                                |           |
| a)        | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No ✓  |
| <b>4.</b> | <b>Compliance History</b>                                                                                            |           |
| a)        | Status of ATR's & any others                                                                                         | No -      |

Overall Rating :

|                                             |     |
|---------------------------------------------|-----|
| Satisfactory (S)                            | ✓ S |
| Satisfactory but requires Improvement (SRI) | —   |
| Unsatisfactory (U)                          | —   |

NAME:

DESIGNATION:

(Signature)