

FIELD INSPECTION REPORT

Date of Inspection: 02.12.2020	District: Patna
Division: Patna	Length (km): 5.750
Name of the Road: N-25 Sijgaon to Dahanu Tola (Kharaiya)	
Scheme Programme: MAINTENANCE	
Package No.: MS-N/2019-20/PATNA/04	Road Id No.:
Status of the Project: Ongoing Completed Under Maintenance	
Work is a case of: New Connectivity Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No In Progress
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U In Progress
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No In Progress
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating : In 4.6 km, surface work completed which is Satisfactory, Rest work is in Progress

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Himanshu
02.12.2020
(Signature)

NAME: Himanshu Raj
DESIGNATION: Assistant Engineer