


FIELD INSPECTION REPORT

Date of Inspection:- 8-12-20		District:- Sheohar
Division:-RWD, Works Div. Sheohar		Length (km):- 7.00 KM
Name of the Road:- Sheohar to Parola Niya		
Scheme/Programme:-		MAINTENANCE
Package No.:-		Road Id No.: 81608108047
Status of the Project:	Ongoing/Completed/Under Maintenance ✓	
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	S/U/Road is partly damaged by flood
c)	Riding Quality	S/U (n)
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutments & Wing walls, Slab in RCC culverts	✓S/SRI/U
c)	Condition of railing/slab/approach for bridges	✓S/SRI/U
3.	Road Furniture	
a)	Whether sing board/informatory/cautionary Board/ Km & 200m stones/Pavement road marking are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	8RI
Unsatisfactory (U)	—

Name:- Dillip Kumar

(Signature)  8-12-20

DESIGNATION:- Junior Engineer