FIELD INSPECTION REPORT

Date	e of Inspection :	03/12/20 Distri	ct: East cham	paran
	sion: Motil	ari Lengt	h (km): 1390 Km	1.
	e of the Road:	10 tihari Madhuban	i Grhat PWD Road	d to Bas
FORMAL	me/Programme: age No.:	Ao fikari Madkubaru MAINTENANCE Road	Id No.:	
	s of the Project:	Ongoing/Completed/Under	Maintenance	
Vorl	c is a case of:	New Connectivity/Up grada	tion/ Maintenance (Ne	w Mainto
SI. N	0.	Parameters to be chec	A STATE OF THE PARTY OF THE PAR	
1.	Pavement	Pavement		
a)	Road Junction	Road Junction condition		
b)	Condition of S	Condition of Surfacing		
c)	Riding Quality			L8/U
d)	Road Camber			\8/U
e)	Whether free aggregates in c	from defects such as vi	sible cracks, exposed	Yes/No N/
)	Contraction Joi	nts provided or not (CC Paver	ment)	Yes/No N/ Yes/No N/
)	Compaction of	flank/slope & raincuts if any		Yes/No
	Cross Drainag	e		-
)	Condition of head walls in Hume pipe culverts including its painting			, S/SRI/U
)	Condition of Abutment & Wing walls, Slab in RCC culverts			JS/SRI/U
:)	Condition of rai	Condition of railings/slab/approach for Bridges		
	Road Furnitur	Road Furniture S/SRI/U		
)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
	Compliance His	itory		-
	Status of ATR's & any others			N/A

>

NAME: Afron Ahmad DESIGNATION: A-E