

FIELD INSPECTION REPORT

Date of Inspection: 02/12/2020 District: East Champaran
 Division: Motihari Length (km): 3.570 Km
 Name of the Road: Bhargawa To Baudha
 Scheme Programme: MAINTENANCE (New)
 Package No.: — Road Id No.: —
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S SRI/U
c)	Condition of railings/slab/approach for Bridges	✓S SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	✓S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Rajendra Prasad Yadav
 DESIGNATION: A.E

Rajendra Prasad Yadav
 02/12/2020
 (Signature)