

FIELD INSPECTION REPORT

Date of Inspection: 03/12/2020 District: East Champaran
 Division: Motihari Length (km): 1.460 km
 Name of the Road: Raipatti To Dymolunwa
 Scheme Programme: MAINTENANCE (New)
 Package No.: Road Id No.:
 Status of the Project: Ongoing / Completed / Under Maintenance
 Work is a case of: New Construction / Upgradation / Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Surface Condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ SRI/U
c)	Condition of railings/slab approach for Bridges	✓ SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory cautionary Board km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Ratendra Prasad Yadav

DESIGNATION: A-E

Ratendra
 (Signature) 3/12/2020

03/12/2020