


FIELD INSPECTION REPORT

Date of Inspection:	2-12-2020	District:	NALANDA
Division :	HARNAUT	Length (km):	2.600
Name of the Road:	PACHAURA MADHUKARI CORNER TO PACHAURA VILLAGE.		
Scheme/Programme:	MAINTENANCE		
Package No.:	MR-N/19-Harnaut/01	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road surface condition	✓S/U	
b)	Condition of Surfacing	✓S/U	
c)	Road width	✓S/U	
d)	Road shoulder	✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregate in case of CC Pavement.	Yes/No	
f)	Condition of Joints provided or not (CC Pavement)	Yes/No	
g)	Condition of flank/slope & raincuts if any	Yes/No	
2.	Culverts		
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railing/slab/approach for Bridges	S/SRI/U	
3.	Road signage		
a)	Whether sign board/informatory/cautionary Board/km & 200m sign board/road markings are provided and maintained	✓Yes/No	
4.	Condition of History		
a)	State of A/R's & any others		

Overall Rating:

Satisfactory (S)		'S'
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		



(Signature)

NAME: MUKESH KUMAR SINHA