

FIELD INSPECTION REPORT

Date of Inspection: 02/12/2020 District: East Champaran
 Division: Motihari Length (km): 4.605 km
 Name of the Road: NH-28 A se Madhya vidyalay Sugaw se Bhimrao Ambedkar Anandiyar
 Scheme/Programme: Vidyalya Murharstoli Mahadalit Basti hote hue Vidya gram Tak.
 Package No.: Road Id No.:
 Status of the Project: Ongoing Complete Under Maintenance
 Work is a case of: New Connectivity Upgradation Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	✓Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓SRI/U
c)	Condition of railings/slab/approach for Bridges	✓S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Rajendra Prasad Yadav

DESIGNATION: A-E

02/12/20
J-E

Rudra
02/12/20
(Signature) AC