FIELD INSPECTION REPORT 08/12/2020 District: Last. Champeran.

Length (Km): 1.760/cm.

(aski pakry to Dhelba Road. Date of Inspection: chakia. Division: Thitcalia Name of the Road: Scheme/Programme: MAINTENANCE Package No.: Road ID No.: Ongoing/Completed/Under Maintenance Status of the Project: New Connectivity/Up Gradation/ Maintenance Work is a case of : Parameters to be checked SI. No. Remarks 1. **Pavement** 151 a) Road Junction condition ` () ' ы Condition of Surfacing c) 101 Riding Quality 5' d) Road Camber Whether free from defects such as visible cracks, exposed aggregates in e) case of CC Pavement. n Contraction Joints provided or not (CC Pavement) 9) Compaction of flank/slope & raincuts if any 2. Cross Drainage 2) NO Condition of head walls in Hume pipe culverts including its painting b) Condition of Abutment & Wing walls, Slab in RCC Culverts c) Condition of railings/slab/approach for Bridges Road Furniture Whether sign board/informatory/cautionary Board/Km & 200m a) Stones/Pavement road markings are provided and maintained 4, Compliance History

Overall Rating :

Status of ATR's & any others

a)

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

Remarks- some Portier damage ducto flood. 2020.

(Signature)

NAME:

DESIGNATION:

OS XII Sense