

FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020		District : East Champaran.
Division : Chakia.		Length (Km): 1.920 Km.
Name of the Road : Mehri Stali Bank se Ketha Mayo Chowk tak.		
Scheme/Programme :		MAINTENANCE (OLD)
Package No.:		Road ID No.: 31708408023
Status of the Project :		Ongoing/Completed/Under Maintenance
Work is a case of :		New Connectivity/Up Gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1,	Pavement	
a)	Road Junction condition	'S'
b)	Condition of Surfacing	'U'
c)	Riding Quality	'S'
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NO
f)	Contraction Joints provided or not (CC Pavement)	-
g)	Compaction of flank/slope & raincuts if any	
2,	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	-
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	-
c)	Condition of railings/slab/approach for Bridges	-
3,	Road Furniture	
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	NO
4,	Compliance History	
a)	Status of ATR's & any others	



Overall Rating :	Satisfactory (S)	
	Satisfactory but requires improvement (SRI)	
	Unsatisfactory (U)	'U'

Remarks - Some portion damage to water logging.

(Signature)

NAME :

DESIGNATION :

 03/12/2020
 03/12/2020
 A. E.