

# FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020		District : East Champaran.
Division : Chakia.		Length (Km):
Name of the Road : Balalwari Passauni to Bilukia Road		
Scheme/Programme :		MAINTENANCE (JLD)
Package No.:		Road ID No.: 3/208408028
Status of the Project :		Ongoing/Completed/Under Maintenance
Work is a case of :		New Connectivity/Up Gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1,	Pavement	
a)	Road Junction condition	'S'
b)	Condition of Surfacing	'S'
c)	Riding Quality	'S'
d)	Road Camber	'S'
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	-
f)	Contraction Joints provided or not (CC Pavement)	-
g)	Compaction of flank/slope & raincuts if any	Yes
2,	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	Yes
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	-
c)	Condition of railings/slab/approach for Bridges	-
3,	Road Furniture	
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	NO
4,	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :	Satisfactory (S)	
	Satisfactory but requires improvement (SRI)	'SRI'
	Unsatisfactory (U)	

NAME :

DESIGNATION :

(Signature)

Zaki  
03/12/2020  
JC

P. M. D.  
03/11/2020  
A.E