


FIELD INSPECTION REPORT

Date of Inspection : 3-12-2020	District: NALANDA	
Division : HARNAUT	Length (km): 8.000	
Name of the Road: Chandi Harnaut NH-30A near Mitki Dar. To Barah hobe hue Sirsi (Cheranagar Naula PWD) Tak		
Scheme/Programme: MAINTENANCE		
Package No.:	Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		✓S/U
b)	Condition of Surfacing		S/U✓
c)	Riding Quality		S/U✓
d)	Road Number		✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Condition of flank/slope & raincuts if any		Yes/No✓
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones & cement road markings are provided and maintained		Yes/No✓
4.	Computer History		
a)	Status of VIR's & any others		

Overall Rating :

Satisfactory (S)		
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		U


 (Signature)