## FIELD INSPECTION REPORT

Date of	Inspection:		District: Callchaufaran,	ma Vilana i	
Divisio	n: Works Div	I amount // // //	1.10 Al Mary		
Name o	of the Road: Bo	kane U-1	To Bokame Khurd		
Scheme	e/Programme:	MAINTENANCE	Lo Bokame Khurd		
Paglings No.			Road Id No.:		
Status of the Project: Ongoing/Complete		Ongoing/Completed	I/Under Maintenance		
Work i	s a case of:	New Connectivity/U	p gradation/ Maintenance		
SI. No.		Parameters to be checked		Remarks	
1.	Pavement				
a)	Road Junction condition			∟S/U	
b)	Condition of Surfacing			VS/U	
c)	Riding Quality			√S/U	
d)	Road Camber			√8/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				
f)	Contraction Joints provided or not (CC Pavement)			Yes/No -	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2	Gross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U				
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			~S/SRI/U	
<b>3</b>	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
學學是	eldmedla disea istil				
a) :	Status of ATR's	& any others		MA	

Overall Rating

Satisfactory (S)	750
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

21/2/20 AB

(Signature)