

# FIELD INSPECTION REPORT

Date of Inspection :	District: East Champaran, Madhubani
Division : Works Division Pakhriyala	Length (km): 1.25
Name of the Road: Dumri-Baitu Pokhar to Hanumanrayana Siwan Road	
Scheme/Programme:	MAINTENANCE (New maintenance Policy - 2018)
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓/A
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	<b>Gross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	- N/A -

Overall Rating :

Satisfactory (S)	✓S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

SALY  
3/12/20  
O.E

Quil  
03/12/20  
A2

(Signature)