

FIELD INSPECTION REPORT

Date of Inspection :		District: <u>East Champaran, Motihari</u>
Division : <u>Works Division Patna</u>		Length (km): <u>1.100 km</u>
Name of the Road: <u>Sikarganj Pitch Road to Balua Primary School</u>		
Scheme/Programme:	MAINTENANCE (<u>new maintenance policy - 2018</u>)	
Package No.:	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No - <u>N</u>
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	- <u>N/A</u>

Overall Rating :

Satisfactory (S)	" S "
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

Sales
3/12/20
S.E

Quil
03/12/20
A2

(Signature)