

FIELD INSPECTION REPORT

Date of Inspection :	District: East-champaran, Motihari
Division : Works Division Patnodaya	Length (km): 3.200 K.M
Name of the Road: Sikarganj Patahi Pitch road AT Dumri to Mahavadi Siva Vin	
Scheme/Programme:	MAINTENANCE (New Maintenance Policy-2018) Mahavadi
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No - N/A
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
	Compliance History	
a)	Status of ATR's & any others	- N/A

Overall Rating :

Satisfactory (S)	✓ S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—


 3/12/20
 S-E


 03/12/20

(Signature)