

FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020		District: West Champaran
Division : Bagaha-2		Length (km): 3.50
Name of the Road: UPsema Katori Boraiya Arshan Se Dharhara mushari to 13		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.: 31809101008
Status of the Project: Ongoing/Completed/Under Maintenance		Completed
Work is a case of: New Connectivity/Up gradation/ Maintenance		Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S S/U
b)	Condition of Surfacing	S S/U
c)	Riding Quality	S S/U
d)	Road Camber	S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	<input checked="" type="checkbox"/>
Satisfactory but requires Improvement (SRI)	<input type="checkbox"/>
Unsatisfactory (U)	<input type="checkbox"/>

Nagendra Kumar
03/12/2020
(Signature)

NAME: NAGENDRA KUMAR
DESIGNATION: JUNIOR ENGINEER