

# FIELD INSPECTION REPORT

Date of Inspection :	3-12-2020	District:	West Champaran.
Division :	Bagaha-1	Length (km):	
Name of the Road:	PWID Road Canal - Balooa		
Scheme/Programme:	MAINTENANCE	3054 (MR) New Maint. Policy 298	
Package No.:	RW/WE/BA4/19/0009	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No✓
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	✓
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature) *Deepak Kumar*  
3-12-20

NAME: Deepak Kumar

DESIGNATION: Junior Engineer