## FIELD INSPECTION REPORT

|                                |  |  | ZHON KEI OKI   |                |
|--------------------------------|--|--|--|----------------|
| Date of Inspection: 02/12/2020 |  |  | District: latora-  |                |
|                                |  |  |  |                |
| Name of                        | the Road: 1/2  | ulwark Mise  | Length (km): 3.22 OKm<br>Lion Road - Osconipar.  | and the second |
| 4.4                            | Programme:   | MAINTENANCE  |  |                |
| 5.4                            | -7.7   | p-21-Danapay   |  |                |
| Status of the Project:         |  | Ongoing/Completed/Under Maintenance  New Connectivity/Up gradation/ Maintenance  |  |                |
| Work is a case of:             |  | The same and the s |  |                |
| Sl. No.                        |  | Parameters to  | be checked   | Remarks        |
| 1                              | Pavement   |  |  |                |
| a)                             | Road Junction condition  |  |  | S/U            |
| b)                             | Condition of Surfacing   |  |  | S/U            |
| c)                             | Riding Quality   |  |  | S/U            |
| d)                             | Road Camber  |  |  | .S/U           |
| e)                             | Whether free from defects such as visible cracks, exposed yes/No aggregates in case of CC Pavement.                          |  |  |                |
| f)                             | Contraction Joints provided or not (CC Pavement)   |  |  | Yes/No         |
| g)                             | Compaction of flank/slope & raincuts if any  Yes/No  |  |  | Yes/No         |
| <b>32</b>                      | =CTOSS Diraina   |  | region (the control of the control o |                |
| a)                             | Condition of head walls in Hume pipe culverts including its painting   |  |  | S/SRI/U        |
| b)                             | Condition of Abutment & Wing walls, Slab in RCC culverts S/SRI/U   |  |  | S/SRI/U        |
| c)                             | Condition of railings/slab/approach for Bridges S/SRI/U  |  |  | S/SRI/U        |
| <b>3.</b>                      | Road Furnitu   | <b>ie</b>  |  |                |
| a)                             | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained  Yes/No |  |  | Yes/No         |
| 4.                             | Compliance 4   | isiory -   |  |                |
| a)                             | Status of ATR  | 's & any others  |  |                |

Overall Rating

| Satisfactory (S)                            |  |
|---|--|
| Satisfactory but requires Improvement (SRI) |  |
| Unsatisfactory (U)                          |  |

World is not started.

Nigns

02/12/20
5. Q.

NAME: Nigmanand Mahto

(Signature)

**DESIGNATION:**