

# FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020		District: Madhubani
Division : Jhunjharpur		Length (km): 2.320 Km
Name of the Road: Lakhnau PWD To Sonar		
Scheme/Programme:		MAINTENANCE
Package No.: MR-N/19-20/Jhunjharpur/03		Road Id No.: 31909802049
Status of the Project:		Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A <del>Yes/No</del>
f)	Contraction Joints provided or not (CC Pavement)	N/A <del>Yes/No</del>
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	N/A S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N/A S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	✓
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)  
03/12/20

NAME: PRAKASH KANT PANKAJ  
DESIGNATION: ASSISTANT ENGINEER.