

FIELD INSPECTION REPORT

Date of Inspection :	02-12-2020	District :	Nakuru
Division :	H/154	Length (km):	7.15 km
Name of the Road:	Chikwama bora b/la rd to Jomo Kando Hamatoo		
Scheme/Programme:	MAINTENANCE	Under Maintenance	
Package No:		Road Id No:	
Status of the Project:	Original Completed/Under Maintenance Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/Maintenance		

S. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	- S
b)	Condition of Surfacing	- U
c)	Riding Quality	- U
d)	Road Camber	- S
e)	Whether free from defects such as visible cracks, exposed subgrade in case of CC Pavement.	Yes - Yes
f)	Construction Joints provided or not (CC Pavement)	Yes - Yes
g)	Comparison of Bank/slope & valance if any	Yes - Yes
2.	Cross Drainage	
a)	Condition of head walls in House pipe culverts including its opening	Satisfactory - S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	Satisfactory - S
c)	Condition of culverts/slab approach for Bridges	Satisfactory - S
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/Lens & 200m stones/Pavement road markings are provided and maintained	No
4.	Compliance History	
a)	Status of ATR's & any others	No.

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SIU)	
Unsatisfactory (U)	U


 02/12/20
 Signature

NAME: Md. Ishtiaque
A-E