FIELD INSPECTION REPORT

	nspection:		District: Hawada	
Division	: Nawe	lala	Length (km): 5 ook y	
Name of	the Road: 1-4	Isua Khanf	our to Sakra	end a discussion merchanismical a
Scheme/	Programme:	MAINTENANCE		College Co.
Package		6 - 10 - 11	Road Id No.: 105026080	72,
All the second second second second	the Project:	Ongoing/Completed	p gradation/ Maintenance	Suppression State Server of Server
Sl. No.	1000 TO 1000 T			Remarks
1.	Pavement			
a)	Road Junction condition			×1:
b)	Condition of Surfacing			*
c)	Riding Quality			\(\frac{1}{2}\)
d)	Road Camber			51
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			YesNo
g)	Compaction of flank/slope & raincuts if any			Yes Vo
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			SISRITU
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			K SRIT
c)	Condition of railings/slab/approach for Bridges			≺ SRI · ·
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Je 1/10
4.	Compliance History			
a)	Status of ATR's & any others			
Ownell	Dating .			
Overall Rating :		Satisfactory (S)	(211)	
		Satisfactory but Unsatisfactory (U	requires Improvement (SRI)	

CRIL Solvator.)
J.R.
RWD

NAME: