FIELD INSPECTION REPORT

D. d. Ci	Inspection: 83 11212620 District: PATNA	-	
Division	inspection. 05 ((2)		
Name of	the Road: Release of Rol form Billa Sheepla PWD R	d to sade.	sopu o
	Programme: MAINTENANCE		
Package	No: Road Id No.:		
Status o	f the Project: Ongoing/Completed/Under Maintenance		
Work is	a case of: New Connectivity/Up gradation/ Maintenance	Remarks	
Sl. No.	Parameters to be checked	a Remarks	
1	Pavement	972	
a)	Road Junction condition	S/2	
b)	Condition of Surfacing	,8/U	
c)	Riding Quality	<i>8</i> 1U	
d)	Road Camber	SA	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	1
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	8/SRI/D	7
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	W.A.
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	1
3.	Road Kurniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	7	1
	D. diver		1
Overall	Rating : Satisfactory (S)	ta de la del	1
	Satisfactory but requires Improvement (SRI)	1)	1
	Kuin	nature)	_
NAME	그 그 그 집에 얼마 되었다면 되었다. 그 그래 얼마를 살아 있다고 있다.		

DESIGNATION: