FIELD INSPECTION REPORT

		District: PATHA	
Date of Inspection:	3/12/200		
Division: DAHAPUR.		Length (km): 3-10 low.	
Name of the Road: Re	pair of load 1	1 H 30 to Gayas pur Load.	
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

SI. No.	Parameters to be checked	Remarks
il	Pavement	
a)	Road Junction condition	SA
b)	Condition of Surfacing	S/Je/
c)	Riding Quality	S/X
d)	Road Camber	SIX
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/Mo
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/J
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200n stones/Pavement road markings are provided and maintained	Yes/No
21514.4°	Gompliance History	
a)	Status of ATR's & any others	10

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Non Mino

31/2/20 31/2/20 A.E. Noner

(Signature)

NAME: Subash chamara 575

DESIGNATION: J-E