

FIELD INSPECTION REPORT

Date of Inspection :	03/12/20	District:	PATNA.
Division :	BARH	Length (km):	3.150
Name of the Road:	NH82 to Kumbha Path.		
Scheme/Programme:	MAINTENANCE	Road Id No.:	10100308072
Package No.:			
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement	✓/U	
a)	Road Junction condition	✓/U	
b)	Condition of Surfacing	✓/U	
c)	Riding Quality	✓/U	
d)	Road Camber	✓/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓/Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	✓/Yes/No	
g)	Compaction of flank/slope & raincuts if any	✓/Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m	✓/Yes/No
4.	Compliance History		
a)	Status of ATR's & any others	No. ATR	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

B Kumar
03/12/20
(Signature) J.E.

NAME: BINOD KUMAR
JUNIOR ENGINEER