

# FIELD INSPECTION REPORT

|                        |                                                          |              |         |
|------------------------|----------------------------------------------------------|--------------|---------|
| Date of Inspection :   | 2-12-2020                                                | District:    | NALANDA |
| Division :             | HARNAUT                                                  | Length (km): | 1.800   |
| Name of the Road:      | CHANDI HARNAUT ROAD N.H-30A TO RUPASPUR VIA CHITIA BICHA |              |         |
| Scheme/Programme:      | MAINTENANCE                                              |              |         |
| Package No. :          |                                                          | Road Id No.: |         |
| Status of the Project: | Ongoing/Completed/Under Maintenance                      |              |         |
| Work is a part of:     | New Connectivity/Up gradation/ Maintenance               |              |         |

| Sl. No. | Parameters to be checked                                                                                       | Remarks         |
|---------|----------------------------------------------------------------------------------------------------------------|-----------------|
| 1.      | Pavement                                                                                                       |                 |
| a)      | General Junction condition                                                                                     | ✓S/U            |
| b)      | Condition of Surfacing                                                                                         | ✓S/U            |
| c)      | Finishing Quality                                                                                              | ✓S/U            |
| d)      | Prop. Camber                                                                                                   | ✓S/U            |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                   | Yes/No          |
| f)      | Expansion Joints provided or not (CC Pavement)                                                                 | Yes/No          |
| g)      | Condition of flank/slope & raincuts if any                                                                     | ✓Yes/No         |
| 2.      | Culverts Drainage                                                                                              |                 |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                           | ✓S/SRI/U        |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                       | S/SRI/U         |
| c)      | Condition of railings/slab/approach for Bridges                                                                | ✓S/SRI/U        |
| 3.      | Road Furniture                                                                                                 |                 |
| a)      | Whether sign boards/informatory/cautionary Board/km & speed pavement road markings are provided and maintained | 200m<br>✓Yes/No |
| 4.      | Accident History                                                                                               |                 |
| a)      | Details of ATR's & any others                                                                                  |                 |

Overall Rating :

|                                             |  |     |
|---------------------------------------------|--|-----|
| Satisfactory (S)                            |  | 'S' |
| Satisfactory but requires Improvement (SRI) |  |     |
| Unsatisfactory (U)                          |  |     |

(Signature)

NAME: MUKESH KUMAR SINHA