

FIELD INSPECTION REPORT

Date of Inspection : 2.12.2020		District: Nalanda	
Division : Rajgir		Length (km): 4.00	
Name of the Road: Re Pair of road from Nalanda Ben sare to Masua PVR			
Scheme/Programme: MAINTENANCE		five years	
Package No.:		Road Id No.: 10200908047	
Status of the Project:		Ongoing/Completed/Under Maintenance ✓	
Work is a case of:		New Connectivity/Up gradation/ Maintenance ✓	
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		✓S/U
b)	Condition of Surfacing		✓S/U
c)	Riding Quality		✓S/U
d)	Road Camber		S/U ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No/H/A
f)	Contraction Joints provided or not (CC Pavement)		Yes/No/H/A
g)	Compaction of flank/slope & raincuts if any		✓Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U ✓
c)	Condition of railings/slab/approach for Bridges		S/SRI/U ✓
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No ✓
4.	Compliance History		
a)	Status of ATR's & any others		—

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

[Signature]
2/12/2020
(Signature)

NAME: Shiva Prakash Gupta

DESIGNATION: A.E.