

FIELD INSPECTION REPORT

Date of Inspection : - 2.12.2020 District: - Nafanda.
 Division : - Rajgir. Length (km): - 5.100 k.M
 Name of the Road:- Repair of Road from Durgapur Chark to Sakul'saray via Kerna village.
 Scheme/Programme: MAINTENANCE
 Package No.: Road Id No.: - 10200908050.
 Status of the Project: Ongoing/Completed/Under Maintenance - Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S
b)	Condition of Surfacing	✓ S
c)	Riding Quality	✓ S
d)	Road Camber	✓ S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No (NA) ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No (NA) ✓
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No


Overall Rating :

Satisfactory (S)

S

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)


 2.12.20
 (Signature)

NAME: - Kishor Kumar
 Assistant Engineer
 Giriyak.