


FIELD INSPECTION REPORT

Date of Inspection : - 2.12.2020 District : - Nalanda.
Division : - Rajgir. Length (km) : - 1.500 km
Name of the Road : - Repair of Road from Kadrisarai panchi road to Wersajith road.
Scheme/Programme : MAINTENANCE
Package No. : Road Id No. : - JD200908051.
Status of the Project : Ongoing Completed Under Maintenance Under Maintenance
Work is a case of : New Connectivity Up gradation Maintenance Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S
b)	Condition of Surfacing	S (SRI) ✓
c)	Riding Quality	S (SRI) ✓
d)	Road Camber	✓ S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No (NA)
f)	Contraction Joints provided or not (CC Pavement)	Yes/No (NA)
g)	Compaction of flank slope & runouts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings slab approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards-informatory cautionary Board km & 200m stones Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :
Satisfactory (S)
Satisfactory but requires Improvement (SRI) **SRI**
Unsatisfactory (U)


2.12.20
(Signature)

NAME : - Kishor Kumar
Assistant Engineer
Kadrisarai.