

FIELD INSPECTION REPORT

Date of Inspection : 2/12/2020	District: Nalanda
Division : Raigir	Length (km): 4.00 km
Name of the Road: Repair of road from Katari more Raigir chabilapur to Nekpur	
Scheme/Programme: MAINTENANCE (3054 MR)	
Package No.:	Road Id No.: 10200604024 10200908052
Status of the Project: Ongoing/Completed/Under Maintenance	Maintain
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U (NA)
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U (NA)
c)	Condition of railings/slab/approach for Bridges	S/SRI/U (NA)
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)

S

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Rampreesh Kumar
NAME: SE
Raigir

22/12/2020
(Signature)