

FIELD INSPECTION REPORT

Date of Inspection : 3.12.2020		District: Nalanda	
Division :		Length (km):	
Name of the Road: Repair of Road from Bihari Rajpur (NH 82) to Machhapur via Gorumara			
Scheme/Programme: MAINTENANCE			
Package No.:		Road Id No.: 10200308055	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		N/A Yes/No
f)	Contraction Joints provided or not (CC Pavement)		N/A Yes/No
g)	Compaction of flank/slope & raincuts if any		N/A Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m	Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		No

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	Satisfactory
Unsatisfactory (U)	

NAME:

श्रीमती अमिता

3.12.2020
(Signature) श्री अमिता
श्रीमती अमिता 30.55 दिनांक