FIELD INSPECTION REPORT

Date of Inspection: 03/12/2020 Division: Mohania			District: Kainure Length (km): 10.450 b			
					(M	
		ssathera - Mul	throom Link Roc	A THE RESIDENCE OF THE PARTY OF		
Scheme/Programme: MAINTENANCE				1-3054		
Package No.: Status of the Project: Ongoing/Complete		Road Id No.:				
The second control of		d/Under Maintenance Up gradation/ Maintenance				
Sl. No.		Parameters to	×		Remarks	
1.	Pavement			Kemarks		
a)	Road Junction condition			√ S/U		
b)	Condition of Surfacing			S/U s		
e)	Riding Quality			√S/U		
d)	Road Camber			. VS/U		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No		
f)	Contraction Joints provided or not (CC Pavement)			Yes/No		
g)	Compaction of flank/slope & raincuts if any			Yes/No		
2.	Cross Drainage					
a)	Condition of head walls in Hume pipe culverts including its painting			S/SKI/U		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			√8/SRI/U		
e)	Condition of railings/slab/approach for Bridges			√8/SRI/U		
3.	Road Furniture					
a)	Whether sign boards/informatory/eautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No S		
4.	Compliance History					
7)	Status of ATR's & any others			No		
(No. am. II	D a time.	100 C	er a land to the collection of the state of			
Overall	Kating :	Satisfactory (S)	A THE STATE OF THE			
		Satisfactory but	requires Improvement (S	RI)	SRI	
		Unsatisfactory (U)		menden diser in Lindbring 12 pt training als of debrace training	

Some polo are devloped in the real Read territure not maintained.

(Signature) 03/12/2020

AE

NAME: Md. Jamil Abul Hassay