## FIELD INSPECTION REPORT

|                     |  | FIELD INSPE      | CTION REPORT                          | raimon               |
|---------------------|--|------------------|---------------------------------------|----------------------|
| Date of Inspection: |  | 3/1420           |                                       | 10.72 M              |
| ivision :           | . 4  | or and y         | Length (km):                          | W 33 )               |
| lame of th          | he Road:   | Chelsi           | 79 to Devagne                         |                      |
|                     | rogramme:  | MAINTENANCE      | Road Id No.:                          |                      |
| Package N           | be Project:  | Ongoing/Complete | ed/Under Maintenance                  |                      |
| Work is a           |  | New Connectivity | /Up gradation/ Maintenance            | The Samuel Character |
| Sl. No.             | No. Parameters to be checked   |                  |                                       | Remarks              |
| 1.                  | Payement   |                  |                                       |                      |
| a)                  | Road Junction condition  |                  |                                       | √\$/U                |
| b)                  | Condition of Surfacing   |                  |                                       | √S/U                 |
| c)                  | Riding Quality   |                  |                                       | √S/U                 |
| d)                  | Road Camber  |                  |                                       | √\$/U                |
| e)                  | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         |                  |                                       | ed Yes/No            |
| f)                  | Contraction Joints provided or not (CC Pavement)   |                  |                                       | ✓Yes/No              |
| g)                  | Compaction of flank/slope & raincuts if any  |                  |                                       | √Yes/No              |
| 2                   | Cross Drainage   |                  |                                       |                      |
| a)                  | Condition of head walls in Hume pipe culverts including its painting   |                  |                                       | ng S/SRI/U           |
| . b)                | Condition of Abutment & Wing walls, Slab in RCC culverts   |                  |                                       | S/SŘI/U              |
| (c)                 | Condition of railings/slab/approach for Bridges  |                  |                                       | S/SRI/U              |
| 3.                  | Road Furniture   |                  |                                       |                      |
| a)                  | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained |                  |                                       | Om Yes/No            |
| 4.                  | Compliance History   |                  |                                       |                      |
| a)                  | Status of ATR's & any others   |                  |                                       | No                   |
| Ouerall             | Pating   |                  |                                       |                      |
| Overan              |  |                  |                                       | SPE                  |
|                     |  |                  |                                       |                      |
| Overall             | Rating   | Satisfactory (S  | ut requires Improvement (\$RI)<br>(U) | (Signature)          |