FIELD INSPECTION REPORT

Date of	Inspection:	3.12.20	District: Grayer	
Division: Graya			Length (km): 9,40 K.M.	
Name o	f the Road: Fa	tehpur thanato	Dymori chatli High level &	bridge
Scheme/Programme: MAINTENANCE			E 3054 MIR (old)	d
Package			Road Id No.:	
			der Maintena	
Physical St.	a case of:	New Connectivity	y/Up gradation/ Maintenance M	aentenance
Sl. No.	Parameters to be checked			Remarks
1.	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			ed Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction o	f flank/slope & rain	Yes/No	
2.	Cross Draina	ge		
a)	Condition of head walls in Hume pipe culverts including its painting			ng S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U N
c)	Condition of ra	ailings/slab/approac	ch for Bridges	S/SRI/U N
3.	Road Furnitu	re		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			m Yes/No
4.	Compliance History			1/4/8/8/8
a)	Status of ATR's & any others			NO
Overall	Rating :	G-41-fo-town (S)		
S		Satisfactory (S)	requires Improvement (SRI)	S
		Unsatisfactory ou	The second secon	

(Signature)