

FIELD INSPECTION REPORT

Date of Inspection : - 3.12.2020 District : - Nalanda.
 Division : - Rajgir. Length (km) : - 4.250 K.M
 Name of the Road : - NH-31 (Pawapuri) Dashrathpur se Saidih Tak.
 Scheme/Programme: MAINTENANCE
 Package No.: Road Id No.: - 10200908036.
 Status of the Project: Ongoing Completed Under Maintenance Under Maintenance
 Work is a case of: New Connectivity Up gradation Maintenance Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S I
b)	Condition of Surfacing	✓ S I
c)	Riding Quality	✓ S I
d)	Road Camber	✓ S I
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes No (NA) ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes No (NA) ✓
g)	Compaction of flank slope & raincuts if any	✓ Yes No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S SRI
c)	Condition of railings slab approach for Bridges	✓ S SRI
3.	Road Furniture	
a)	Whether sign boards-informatory cautionary Board km & 200m stones Pavement road markings are provided and maintained	✓ Yes No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

SRI


 3.12.20
 (Signature)

NAME: - Kishor Kumar
 Assistant Engineer
 Goriyakh.