

FIELD INSPECTION REPORT

Date of Inspection : - 3.12.2020 District:- Nalanda.
 Division :- Rajgir. Length (km):- 0.990 k.M
 Name of the Road:- Giriyak prakhari ke Andrapat NH-31 se purani Ank
 Scheme/Programme: MAINTENANCE path Nirman karya.
 Package No.: Road Id No.: - 10200908038.
 Status of the Project: Ongoing Completed Under Maintenance Under Maintenance
 Work is a case of: New Connectivity Up gradation Maintenance Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SI
b)	Condition of Surfacing	SI (SRI)
c)	Riding Quality	SI (SRI)
d)	Road Camber	SI
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No (NA)
f)	Contraction Joints provided or not (CC Pavement)	Yes/No (NA)
g)	Compaction of flank slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings slab approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

SRI


 3.12.20
 (Signature)

NAME:- Kishor Kumar
 Assistant Engineer
 Giriyak.