

FIELD INSPECTION REPORT

Date of Inspection :	02/12/2020	District:	Muzay
Division :	Muzay	Length (km):	1.00
Name of the Road:	Repair of road from Jamalpur Sherkhan main road to house of Nasseh Paswan via Samudai K Bhawan.		
Scheme/Programme:	MAINTENANCE	M/12 - 3054	
Package No.:		Road Id No.:	20801708163
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U R2
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No S
f)	Contraction Joints provided or not (CC Pavement)	Yes/No S
g)	Compaction of flank/slope & raincuts if any	Yes/No S
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/UG
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/UG
c)	Condition of railings/slab/approach for Bridges	S/SRI/UG
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	R.I Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	21-12-2020 HRE H-38 6011-40 ATR 21-12-2020 HRE H-38 6011-40 ATR

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	'SRI'
Unsatisfactory (U)	

MD. ALI ANWAR

NAME:

(Signature)