

FIELD INSPECTION REPORT

Date of Inspection : 02/11/20 District: Nalanda.
 Division : Patna Length (km): 1.070.
 Name of the Road: Nalanda. Barragari Path to Normal bigha.
 Scheme/Programme: MAINTENANCE
 Package No.: Road Id No.: 10200908041.
 Status of the Project: Ongoing Completed Under Maintenance Under Maintenance.
 Work is a case of: New Connectivity Up gradation Maintenance maintainable.

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings slab approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No.

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

SRI

Satish Kumar.

(Signature) 02/11/20