

FIELD INSPECTION REPORT

Date of Inspection : 03.12.2020 District: Saharsa
 Division : Saharsa Length (km): 0.900 km
 Name of the Road: Repair of Rd from NH-107 to Jaiwar Navoday Vidyalay School Baripahi
 Scheme/Programme: MAINTENANCE
 Package No.: Road Id No.: 20904308091
 Status of the Project: Ongoing Completed Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/V
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/V
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N.A.
f)	Contraction Joints provided or not (CC Pavement)	N.A.
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting.	N.A.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N.A.
c)	Condition of railings/slab/approach for Bridges	N.A.
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	U

(Signature)
 03/12/2020

NAME: MD. NASIM AKHTER
 Assistant Engineer