


FIELD INSPECTION REPORT

Date of Inspection : 3-12-2020	District: Purnea
Division : Baisi	Length (km): 10.400
Name of the Road: Repair of road from Talil Chowk to Pharambaid via Magama Piyali	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.: 21105408042
Status of the Project:	Ongoing Completed Under Maintenance ✓
Work is a case of:	New Connectivity Up gradation Maintenance ✓

SL No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U


 (Signature)
 A.E. Baisa

NAME:
 Asim Kumar